

FIG. 1






Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002



3/4

FIG. 3



or Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002



404 406 otal Produced in Current Shift Total Produced in Last Shift Total Disc's since 6:30 AM Line Status Today (Above Target) Today (Below Target) Total Quality fail quantity for 3:00:00 AM 06:30:00 AM 11/15/2001 883 6241 6241 嚣 0 Target Down Times Start Times Yesterday .; 11:00:00 PM 11/14/2001 ∇ A Green triangle indicates the current day's average
∇ A Blue triangle indicates the previous day's average
∇ A Red triangle indicates maximum number allowed 402 07:00:00 PM 11/14/2001 3:00:00 PM 11/14/2001 (@) GE Operation Services Optimization Technology & Services 11:00:00 AM 11/14/2001 Double Side Defect Dummy Side Spot 🖒 Overflow Stain Surface Scratch Lacquer Machine Metal Scratch Metal Spot Bonding Gap Inclusion Injection Flaw Surface Spot 7:00:00 AM 11/14/2001 3:00:00 AM 11/14/2001 11:00:00 PM 11/13/2001 7:00:00 PM 11/13/2001 뚪 중쫎 3:00:do PM 11/13/2001 Short Term Defects: Number per last 100 Shape Regulator V Supervisor External Y 🔀 11:00:00 AM 11/13/2001 Spacer Layer (DVD-9 only) SL ID: Too Low SL ID Defta: Too High Handling Fault Tang. Dev. OD: Too High SL OD: Too High Rad. Dev. OD: Too High Rad. Dev. OD: Too Low Tang. Dev. ID: Too High External Z Rad. Dev. ID: Too High 经 Rad. Dev. ID: Too Low File Screens Window Help Instantaneous Yield 100.0 2g Dashboard PPO DB Handling 90.0 **80.0** 70.0 -0.00 &유 ន្តន

. O L